




# 4F27E-FN4A-EL FN5 PO741 TCC SLIP CT-27 CT-30


### TORQUE CONVERTER APPLIED










### STATOR IMPELLER SIDE









### APPLY SIDE OF PISTON







# COVER







#### TORQUE CONVERTER APPLIED
























TOYOTA A-340 SERIES 1987-1999 TRANS FLUID OVERHEAT TORQUE CONVERTER BLUE TO-27 FAMILY


# DIAGNOSIS

- Check cooler flow GPM with TCC ON
  - Standard is 1 qt per 20 seconds which equals .5 to .6 GPM
  - High mileage Toyota A-340's will typically run .3 to .4 GPM or below which will cause the AT Temp light to come on


















TO COOLER ORIFICE


ENLARGE THIS ORIFICE .040" TO .050" LARGER THAN THE ORIGINAL SIZE

O.E. DIAMETER
IS .059"
(ORIFICE SIZE MAY VARY)





TOYOTA A-340 2000 & UP V-8 P0770 TCC SLIP TO-61







# TCC PASSAGE I.D.








# STATOR-IMPELLER SIDE





















### **TURBINE**












## TOYOTA A-245/246 DTC PO770 T0-39

### A-245 PORT I.D.





### STATOR BUSHING






ISUZU 4L30-E 2000 & UP EC3 PARTIAL ENGINE STALL TORQUE CONVERTER BLUE **B-25-WOVEN OR** HIGH CARBON LINING













### PWM TCC "OFF" PARTIAL SCHEMATIC




### PWM TCC "ON" PARTIAL SCHEMATIC













### VW/AUDI 01M/01N/01P PARTIAL ENGINE STALL RE-10

EV4




SOLENOID FEED



The Torque Converter Clutch may be partially applied when EV4 is partially restricted












# VW/AUDI 01M/01N/01P EXTREMELY INTERMITTENT P0740/01192 RE-10









### CONVERTER CLUTCH APPLY CIRCUIT



