

The 80- 20 Rule

sonnax®

Bob Warnke

TCRA

4.16.16

The 80 – 20 Rule

- 80% of your converters will never have TC issues.
- 20% that have clutch apply or pressure related issues, will likely be valve body or pump control issues.
- 80% of initial apply issues, may be resolved by resetting adapts.
- 20% of your customers will likely claim 80% of the problems.
- 80% of this material is available on-line and 20% is new or verbal.
- 80 pages in print, 20% will may be reviewed today.

Diagnositics and Control of TC Clutch:

1st: Identify the type of converter .

2nd: Identify the condition of failure.

3rd: Options to isolate the problem.

Transmissions included here:

ZF 9 HP 48- Jeep Cherokee, Chrysler 200, Caravan '16

ZF 8 HP 45/90, Dodge truck, up to 2500.

GM 6T30/40/45/50

GM 6T70

GM 6L45/90

Ford 6R60/80 & ZF 6 HP

Type of Converter

- TC clutch design;
Two path (pass)- Clutch fixed to damper.
Three path- Clutch fixed to the damper.
(AX4S, CD4E, Honda)
Three path- Clutch fixed to cover.

Two Path

Turbine fixed to Damper or turbine hub.

Examples:

Two Path, Turbine fixed:

4T65E

4L60/70E

4L80E

5L40E

48RE

45/545/68RFE

41TE

TF81SC

U140-U660 etc.

5R55W

4R100


5R110

Three path, Turbine fixed:

CD4E

AX4N

Honda



**ZF 6 HP- 26 – Two path.
Friction loaded**




**Ford 6F35-Two path
Floating piston**



722.6 / 722.9

Three path, multi-plate clutch, piston extends from the cover.

Applications:
RE5R05A
AS68RC
ZF 8 HP
6R140
Etc.



Design concern: Cannot have excess leakage into the piston area or centrifugal force will create piston travel. .

Failure Modes



Run-away Heat



Excess slip or poor pressure control = heat.



Poor flow, excess tolerance = inefficiency.& heat.



Over-load




Excess apply pressure = piston distortion & lining failure.




Overloading = cover distortion.


Examples of: Excess converter charge and apply pressure:



Excess converter charge pressure = cover distortion, ballooning.



Poor material and high pressure = Turbine hub thrust and pulled blades.



Excess apply psi. distorts TC piston. Friction should apply from the outer edge inward.





Excess apply psi. = Bent TC piston

Failure Review

- 100% efficiency, is when the TC piston is locked to the cover.
- A differential in engine RPM to turbine shaft RPM causes heat.
- Smooth gear change requires either slipping/open TC clutch or progressive damper spring rate.
- Converters are remaining applied for tow-haul, mid-sized vehicle engine braking, start stop, neutral idle and may not open during shifts.
- Many CVT's with TCC converters, lock after 15 mph and remain applied.
- Under pressurization causes high stall, poor acceleration,overheat.
- Excess pressure causes TC piston and cover distortion.


- More speeds and reduced converter slip improve economy.
- More shifting and control over converter clutch slip, leads to increased valve body and solenoid activity.
- Shift overlap, without TCC slippage, causes drive-ability problems.
- As the valve body & TEHCM wear, shifting and converter control is lost.
- The TCM or TEHCM can only adapt for point.



Isolating control issues:

- Programming vs. TCM vs. Solenoid vs. Hydraulics.
- Checking cooler flow and release pressure indicate two different issues.

What is the root of the problem?



Computer program and VIN match.



Audi- ZF 6, TCM, Contamination and terminal solder issues.




6T30, solenoid contamination



Valve bore wear




ZF 6- Pump circuit cross leaks.



APPLICATION: HONDA 4 & 5 speeds, Odyssey Illustrated.

Sonna-flow,
Cooler flow



Event: Hot idle, Park Hot idle, R & D Accel. 1,2,3,- Cruise 4 & 5 TCC Apply Stop & Go

Condition: _____
_____ Poor release oil flow ----- Proper release oil flow _____

Correction: _____


Notes: Prior to Sonnax line to lube pressure regulator valve -90892-04K, operating temperature high 240-360f.

_____ After valve body upgrades -180f. Maximum Concerns, TCC lining failure, overheat code, TC 740 Code, TCC shudder


Honda; Line to lube pressure regulator valve.
Honda utilizes a three path converter.

Figure 7 **Sonnax Lube Regulated PR Valve, Corrected Low Flow Condition**

The Sonnax lube regulated PR valve 98892-04K corrects the low flow condition by allowing the internal relief valve to provide flow to converter before converter charge circuit is fully open.



3 solenoids are actuated in this .8 seconds
Vent to Exhaust, Clutch apply, and TCC apply




During the shift ,TC slip is opened.

After shift ,TC is closed.

ZF 9 HP48- Converter Release Pressure Test Data

Converter Release Oil, ZF9HP45 '15 Jeep Cherokee 3.2 ltr.



Converter flow is required to control heat.
The pump and valves control pressure and flow.

Testing flow indicates:


TC clutch release clearance

TC valve position and orifices.

Pump and filter capacity.

Condition of converter feed and exhaust.


Cooler restriction



Three path oil flow

TR60SN, ZF 8HP, AS68RC, 722.6/9, RE5RO5A, 6R140.

Piston fixed in, moves away from the cover



Need to become familiar with the controlling inputs and data obtainable from the transmission.


Scanner information from a road test may not be sufficient!

- Calculated torque is more important today.
- Speed sensor input and tire size/pressure.
- TC slip RPM.
- What is normal? When is TC supposed to be open /closed ?
- TC solenoid control. The need to scope known good.
- Converter pressure. “ “
- Cooler flow “ “
- Factory updates?
- After-market experience?
- Is this a two path or three path converter?

Programing Terminology

- Reprogram: This is required to match the VIN, when a Mechatronic or TCM has been replaced.
- Re-flash: OE manufacture has developed a software update to improve or overcome a drive-ability complaint in an existing program.
- Reset Adaption: This brings OE program back to base level and restarts the learning process over.
- Quick Learn: Fast learn process, much of which is static or first shift sequence.
- Adaption: A long learn process. Must obtain operating temperature before it will start adaption. Generally require 10 up/down shifts under all throttle angles to be as required and comfortable.

Example of ZF 6, TCM Adaption




Unit Specifics

ZF 8 HP 70/80 Converter

Dodge 2500 truck and BMW 5/X series

This is a three path converter, clutch is within the cover



ZF 8 HP 45/70


Dodge, Jeep 2011 >

Three Path Converter



- ZF 8 HP could have the optional A clutch dis-engagement (neutral at stop). The units will have a nitrogen accumulator in the pan. This charges lube and pump pressure at idle in drive. This type of system will also affect converter load at idle, as the A clutch is brought back on. NVH will be a “point of concern” on this as well as other units using Neutral in Drive.

Splined hub for pump drive sprocket





Stator spline

Turbine shaft/TC piston




WK


6R140 pumps



ZF 8 & 6R140 Impeller hub (similarity and precautions)



ZF 8HP Converter release pressure



P ZT tap is the only pressure port available. It monitors converter charge, in this three path converter.

Monitoring converter charge is an indication of pump, filter, pressure regulation, lockup valve, solenoid and the converter clutch piston seal condition.


OE notes minimum of 15 psi. or 1.0 bar, max of 87 psi. or 6.0 bar. That min/max will depend on SV/ TCC valve position.

Past experience: Any leaks within the converter, stator or valve body that allow residual oil to become trapped behind the TC piston will create a partial clutch apply, because of centrifugal force. That can result in harsh shifts or driveline vibration. (NVH)

VK top cooler line: To cooler
ZK bottom cooler line: Return from cooler

INSERT



ZF 8- Converter charge pressure. Pz T



ZF 8 HP Mechatronic TCC factors:

WK- Is the TCC solenoid




Red; Valves in the ZF8, that affect TC control and TC apply. This is a three path converter!



ZF 8 HP 45

Noted problems:
Solenoid failure, Clutch regulator and solenoid regulator bore wear.

No valve here
in this
application.




Yellow Painted heads, remove VB from case.

ZF 8 TCM Issues



Loose
termination
solder points.



Range switch module
failure.

GM 6T30/40, and 6T70 Scanner,

Focus on these parameters:


- Tap Cell # :
 - 0 to 4, no adjustments or concerns
 - 5 to 10, adaption in process, reset and monitor rate of adjust.
 - 11 >, Concerns; possible codes in history files.
- Check Input signals.
 - 3/5/Rev material collects on the input magnet first.
- Clutch shift time:
 - Normal is .2 to .8 seconds.
- Monitor TCC slip rate:
 - Normal is 18 to 30 RPM w/ light accel.
 - Full apply/cruise will go to -0-.



6T40 Cooler flow

APPLICATION: 6T40 (2012– Chev. Cruise)

©2008 Sonnax® 800/843-2600 • 802/443-9722 • fax: 817/463-4679 • www.sonnax.com • info@sonnax.com




Condition: Normal cooler flow.

Notes: Return cooler line enters rear of the case. TCC solenoid ramp on just after 1-2 shift. TCC remains applied on Coast down shifts until 3-2 or 2-1. Depending on load, applied TCC may have a regulated slip of 20-80 rpm! TCC control strokes first. TCC regulator controls slip rate.

6T30/40



No Lockup, Code 741

Before transmission removal: Check cooler flow !
After cooler flow, remove TEHCM and air check TCC valve.




Low air pressure
supplied here:

Should stroke TCC
control, then valve
should return.




6T40 Pressure switch failure.

Gear ratio or implausible gear codes.



Gen 1, Early, without thimble type switch



Left: early straight leg.
Right: late spring type
Both are Gen 1.

All switches are N.C.
Normally closed.


Place ohm-meter
lead outside each
leg rivet.

Push on film with
pencil eraser. Switch
should open.

Film distortion and
contamination set
switch codes..



Gen I, Late thimble and o-rings.
Star is TCC solenoid




6T40/50 Solenoid Components

Contamination is a problem when the 3 5 Rev waive plate breaks.



1. Solenoid retainers can be pulled out, once the gasket is removed.
2. Solenoids can be opened to clean, by bending back the crimp on the can.
3. Solenoids are coded. Each flow rate number on the canister, is programmed into the TCU. Exchanging requires adaption and/or re-flash.

6T30/40- Vacuum test at the red lines on casting.
Common valves with bore wear.





6T30/40 Pump and Valves.

Known to develop bore wear at these locations:


Example: TC control starts to move at 16 psi.

At 22 psi it is at full stroke. If the bore is worn or the TCC solenoid feed is bad, the valve may stall part way which cuts off converter flow.



6T30/40 Turbine Shaft, TCC seal.


Caution, not to damage this seal when loading the turbine shaft and case half.



6T30/40 No TCC application and or Code 741: Post repair, metal clad seal damage






Converter turbine hub seal to turbine shaft.



Pump stator seal. Easily damaged as bell housing is lowered onto the lower assembly.


6T40

Pump bushing and Converter impeller hub alignment



Verify no wear present at these surfaces! These control alignment. Excess wear will create pump bushing and converter hub leaks.

6T70 Pressure



6T70: Line Pressure Specifications

Requested (kPa via Line solenoid:	Desired Line tap psi.:
0	50-130
200	100-130
400	160-190
600	220-250
1000	270-300


Known causes of low line pressure:

Contamination of the relief ball in the pump.

Pump outlet to case seal leaking.


Mis-assembly of pump drive chain.

6T70 TCC circuit air test




6T70 Pressure switch service & testing

Switch failure is common. Implausible gear or gear ratio codes.
Also TCC may not be functional depending on the sequence of failure.





5 pin pressure switch terminal access here.



At rest each switch is 2.2 to 8.0 ohms. Depressing the film they should open to 0.0. As viewed here, ground pin is on the right. Moving toward left, each switch has it's own power leg.

6T70, Gen 1

Inspect for bore wear and broken isolator spring.



6T70, Gen 1



9 check balls at the pins.

3 actuator feed accumulator pistons within the circles. .




Look for gasket damage due to check ball contact here.

TCC oil control



TC Release oil is controlled by the bushing and driven sprocket seal.


6T70 Drive sprocket support seal for TCC release oil.



Easily damaged, thin wall housing with Teflon insert. Causes code 741


The ball bearing for this gear is not serviced separately !

6T70- Turbine hub ID, has an internal bushing and seal contact area. This controls TC charge and apply pressure.





6T70-

Pump drive relationship to converter/apply charge oil.



sonnax[®]

6T70- Front Differential Gear Support



The stator is the pilot for the converter hub bushing. The stator is centered in the case by the machined step in the bell housing. That step matches the gear support. It is critical the case is not worn. The support should not move over .002" .

6T40/45/70 Converter

6T70 slightly different, but does have the metal clad lip seal pictured in previous slide, which is easily damaged. Converter should be loaded horizontally.



Converter Damper Issues



6T70/75 Damper- Top
Ford 6F50 Bottom left.
Note: The spring seat failure.


GM 6L45/80/90

Shift Quality & Torque Converter Clutch
concerns:

6L80/90, Cooler flow

APPLICATION: 6L90, 2011 truck w/tow pack

GPM/HZ



Condition: Normal drive & TCC control


Correction: Note: TC clutch may not cancel with brake or on deceleration!

Notes: Cooler return is lower on Bell housing, flow increase by .2 to .5 gpm. At TCC apply. Suggest use of graphing multi meter or Snap-On Vantage set at 500 Hz scale.


6L90- Pump converter clutch valve.

Complaint: 741 TC Code, No TC apply, engine stall.

Cause: Pump valve sticking.



The 6L45/6L90 TCC signal circuit can be air tested on the pump. This port dead-ends at the TC control valve. With low air supply, should hear TC control valve stroke and return. (the smallest diameter port here)



GM 6L50/80/90

Complaint: Overheat, TCC slip codes




Orifice plug missing from under this hole.
Known to fall out if stator is removed.



6L45/90 - Pump valves.

Known bore wear.



TCC Control, tends to stick



Line psi. relief

Converter feed limit. Control of release pressure, not TC apply pressure, nor slip rate!

Pressure regulator valve and bore wear = High or erratic pressure and reduced converter charge.

6L80/90 valve body


For TCC and drive-ability concerns, inspect the following bores:



AFL

6L45/90 pressure switch tests

The circuits can be tested using a low impedance ohm-meter.



1: Remove the gasket plate.

The exposed switch circuits are circled.

The right has three blades, the left has two.


2: Place the ground side of the ohm-meter on right outer blade. The plastic cover has pin-holes, which can be used to hold the tip of the probe.

3: At rest each switch will have 3.5 to 8.5 ohms. When the red switch film is depressed with an eraser, resistance will go to -0-.



Ohm-meter probe tip, resting in pin-hole.

6L45/90 TECHM exploded view




★ TCC solenoid



Connector locking tab is removable. Reports of these breaking, so save your cores!


ZF 9 HP48- Converter Pressure Test Data

Converter Release Oil, ZF9HP45 '15 Jeep Cherokee 3.2 ltr.



ZF9 HP 48

Valve body removal and converter circuit Id.




OTA, (oil to water) cooler, cut-away.
Rear ports are water access.
Front (below the cover) ATF flow.



ZF 9 HP Valve body, manual park type

exploded view



Valve identification,
(Top down)

Limp home valve

Pressure transducer terminal

C clutch valve

D clutch valve

B clutch valve


Solenoid pressure regulator

Shift valve system pressure

ZF 9 HP 48, Manual park type

Valve identification,
(Top down)

- Main system Press. Regulator
- Lubrication valve
- Converter switch valve



ZF 9 HP 48, Manual park type



Solenoid Identification, (Top down):

Sys: Solenoid, System Pressure

TCC, Converter clutch control. ★

B solenoid- Rear driving clutch-on in 3,5,9, Rev

E solenoid- Front driving clutch-on in 4 to 9.

A solenoid- Dog clutch, Front- on 1 to 7.

F solenoid- Dog clutch, Rear- on all, except 5 to 9

D solenoid- Rr. Large brake.- on all except 2 to 6

C solenoid- Rr. small brake- on 2,6,8 & braking

LHM solenoid- limp home sold.

Valve identification, (Top down)

Lockup clutch regulator

E clutch valve

A clutch valve

F clutch valve

Testing information:

- ZF 9 HP45 Notes:

The external design cooler has a thermal bypass valve in it. If that cooler is flushed or replaced converter temp and cooler out will have to exceed bypass temp opening (est .125 f) in order to charge the cooler and avoid an under fill.

Filter is internal!

Fluid capacity, 6.0 ltrs./12.7 qts. Part # 68157995AB Miller dipstick# 10323A


Fill plug is over the differential. Drain plug is under bell housing area.

Not all cases have the three bell housing to case pressure taps! Some only have the converter pressure.

ZF 9 HP 48, Common problems:


- Harsh shift concerns: Fix = Reflash
- Loss of Reverse, 1st, 7,8,9 = Snap ring blown from C clutch case groove. Updated snap ring.
- Neutral after coast down; Fix = Reflash, if not resolved replace external TCM.
- Anytime the valve body or transmission has been serviced, Adaption must but be reset and Adaption memory cell's cleared.
- Do not confuse adaption reset with “valve body solenoid learn” . This matches the solenoids to the TCM. Do not relearn solenoids when the transmission, as an assembly has been replaced! Solenoid relearn will erase all factory settings!
- If the adaption memory cell counter is -0-, then that cell has not been updated.

ZF 8 HP 70/80 Converter Destined for Dodge 2500 truck



ZF 8- Converter charge pressure. Pz T

Converter Release PzT ZF8HP '15 Jeep Grand Cherokee dsl. Three Path Converter PzT pressure



ZF 8 HP 45/70


Dodge, Jeep 2011 >

Three Path Converter




- ZF 8 HP could have the optional A clutch dis-engagement (neutral at stop). The units will have a nitrogen accumulator in the pan. This charges lube and pump pressure at idle in drive. This type of system will also affect converter load at idle, as the A clutch is brought back on. NVH will be a “point of concern” on this as well as other units using Neutral in Drive.

Splined hub for pump drive sprocket



Stator spline

Turbine shaft/TC piston






Pz T

Transmission Type	Model	Engine Displacement	Converter Kit
ZF-8 HP 45 HIS	335i (F30)	3,0L R6	1090 298 002
ZF-8 HP 45	528i (F10)	3,0L R6	1090 298 031
ZF-8 HP 45	535i (F10)	3,0L R6	1090 298 002
ZF-8 HP 45 HIS	535i (F10)	3,0L R6	
ZF-8 HP 45	535i Gran Turismo (F07)	3,0L R6	1090 298 002
ZF-8 45 HIS	535i Gran Turismo (F07)	3,0L R6	
ZF-8 HP 45 X	535xi (F10)	3,0L R6	1090 298 002
ZF-8 HP 45 X	535xi Gran Turismo (F07)	3,0L R6	1090 298 002
ZF-8 HP 70	550i (F10)	4,4L V8	1090 298 026
ZF-8 HP 70	550i Gran Turismo (F07)	4,4L V8	1090 298 026
ZF-8 HP 70 X	550xi (F07)	4,4L V8	1090 298 026
ZF-8 HP 70 X	550xi Gran Turismo (F07)	4,4L V8	1090 298 026
ZF-8 HP 45 HIS	640i Cabriolet (F12)	3,0l R6	
ZF-8 HP 45	640i Cabriolet (F12)	3,0l R6	1090 298 002
ZF-8 HP 45 HIS	640i Cabriolet (F12)	3,0l R6	
ZF-8 HP 45	640i Coupe (F13)	3,0l R6	1090 298 002
ZF-8 HP 45 HIS	640i Coupe (F13)	3,0l R6	
ZF-8 HP 70	650i Cabriolet (F12)	4,4L V8	1087 298 026
ZF-8 HP 70 H	750i Active Hybrid (F04)	4,4L V8	

sonnax[®]

Transmission Type	Model	Engine Displacement	Converter Kit
ZF-8 HP 90	760i (F01)	6,0L V12	1090 298 007
ZF-8 HP 45 HIS	M 135i (F20)	3,0L R6	
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 002
ZF-8 HP 45 X	X3 (F25)	3,0L R6	1090 298 031
ZF-8 HP 45 X	X5 (E70)	3,0L R6	109 298 002
ZF-8 HP 70 X	X5 (E70)	4,4L V8	1090 298 026
ZF-8 HP 45 X	X6 (E71)	3,0L R6	1090 298 002
ZF-8 HP 70 X	X6 (E71)	4,4L V8	1087 298 026

ZF 8 HP 45





Yellow Painted heads, remove VB from case.

ZF 8 HP Mechatronic TCC factors:

WK- Is the TCC solenoid

Red; Valves in the ZF8, that affect TC control and TC apply.



ZF 6 HP 19/21 and Ford 6R60

Two Path Converter




ZF 6 HP 19/21/26 -TC Release pressure test:

Complaints: Rough idle, drive-line vibration at low RPM/ low speed.
Harsh up or down shifts.

Complaint of bump down on acceleration from stop, or feels like second gear starts.

The pressure test at WK, isolates Hydraulic or Solenoid control from Converter clutch.



Normal WK psi:

P,R,N,D, idle: 76

P,R,N.D, stall: 90

Drive accel, through 1- shift,
72-78 psi.

After 2-3 shift, WK drops to 1.0
to 1.5 psi. After 4th WK is -0-.

Most instances remains at -0-
during up/downshifts. Forced
kickdown, TC opens to 78 psi. for
.5 seconds, then back to 1.5 psi.

TCC control may vary slightly,
dependent on vehicle and
programming.

sonnax[®]

ZF 6 and or Ford 6R60/80

Complaint: Harsh shifts, TCC slip or cycling.



Cause: Incorrect solenoid calibration or defective TCC solenoid.

- Ford 6R80, 2010> Top Mechatronic
- Ford 6R60, 2006 > 2010, Middle.
 - ZF6 HP M version, Lowest
 - TC solenoid has a star on it.




The flow rate between Ford and ZF Bosch solenoids, are not the same.


6HP19/21 Pump and Stator warpage and cross leaks will require inspection as service life is extended.
Circuits in red paint control TCC apply and release.



ZF 6, Gen 1 & Ford 6R60/80




TCC affect or control valves.



ZF 6, Gen II

TC control



ZF6HP19/26/32*

*Also fits Ford 6R100

sonnax

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 449 • Bellows Falls, VT 05101-0449 USA
(802) 943 2600 • (802) 463 9722 • F: (822) 463 4058 • www.sonnax.com

1 95740-05K Oversized Converter Release Regulator Valve Kit

Helps cure:

- Excessive TCC slip, RPM & related codes
- Harsh lockup apply & release

Note: Requires tool kit F-95740-TL5 & the VB-FIX reaming fixture.

2 95740-11K Oversized Lubrication Control Valve Kit

Helps cure:

- Low converter pressure
- Lube failure

Note: Requires tool kit F-95740-TL11 & the VB-FIX reaming fixture.

3 95740-13K Oversized Bypass Clutch Control Valve Kit

Helps cure:

- Converter overheat
- Low TCC release pressure

Note: Requires tool kit F-95740-TL13 & the VB-FIX reaming fixture.

4 95740-03 Pressure Regulator Sleeve

Helps cure:


- Harsh or erratic line pressure
- Broken parts

5 95740-01K Oversized Pressure Regulator Valve Kit

Helps cure:

- Delayed or no reverse
- Poor shift quality

Note: Requires tool kit F-95740-TL & the VB-FIX reaming fixture.



6 95740-17K Oversized Solenoid Pressure Regulator Valve Kit

Helps cure:

- Gear ratio or solenoid codes
- Wrong gear starts

Note: Requires tool kit F-95740-TL17 & the VB-FIX reaming fixture.

7 95740-08K Oversized Clutch D1 or E Control Valve Kit

Helps cure:

- Flare upshifts or downshift bind-ups
- Excessive clutch overlap & clutch distress

Note: Requires tool kit F-95740-TL8 & the VB-FIX reaming fixture.

8 95740-09K Oversized Clutch A Control Valve Kit

Helps cure:

- Flare upshifts or downshift bind-ups
- Excessive clutch overlap & clutch distress

Note: Requires tool kit F-95740-TL8 & the VB-FIX reaming fixture.

9 95740-21K Clutch A Control Boost Valve & Sleeve Kit

Helps cure:

- Delayed/Harsh forward engagement
- Flare/Neutral on 5-4 downshift

10 95740-15K Valve Body Accumulator Piston & Spring Kit

Helps cure:

- Firm up/downshift and/or engagement
- Erratic EDS solenoid control

11 95740-19K

6 large & 6 small plugs

12 95740-25K O-Ringed End Plug Kits

Helps cure:

- Soft/Inconsistent shift feel

©2017 Sonnax Industrial, Inc.

For harsh shifts and TCC concerns, inspect the red valve, bores.

sonnax