

TCRA

2010

sonnax[®]

TECH CALL ISSUES

Presenter: Ed Lee

sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch




sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



sonnax[®]

ISSUE: Rebuilding the new GM Captive Clutch



ISSUE: Rebuilding the new GM Captive Clutch




sonnax

ISSUE: Rebuilding the new GM Captive Clutch




sonnax[®]

ISSUE: 4R100 740 Code




sonnax[®]

ISSUE: 4R100 740 Code




sonnax[®]

ISSUE: Honda 740 Code



sonnax

ISSUE: Honda 740 Code




sonnax[®]

ISSUE: Honda 740 Code



sonnax[®]

ISSUE: Honda 740 Code




sonnax[®]

ISSUE: Honda 740 Code



sonnax[®]

ISSUE: Honda 740 Code



sonnax[®]

ISSUE: Honda 740 Code



sonnax[®]

ISSUE: 722.6

**Cold Stall, TCC Shudder,
Low Speed Vibration, Flair on
Upshift, Drive Shaft Resonance,
Down Shift Shudder**

ISSUE: 722.6



sonnax[®]

ISSUE: 722.6




sonnax[®]

ISSUE: 722.6



sonnax[®]

ISSUE: 722.6




sonnax

ISSUE: 722.6



sonnax[®]

ISSUE: 722.6



sonnax[®]

ISSUE: 722.6



sonnax[®]

ISSUE: 722.6



sonnax[®]

QUESTIONS?

sonnax[®]